



DO NOT DISCARD

Rental Device Return Instructions



MYWOUNDHEALING.COM



Follow these 5 simple steps:

1. Contact 3M at 1-800-275-4524, press 2, dial 45995 to let us know your therapy is complete.
2. Remove canister, double bag it, then discard per local hazardous waste laws.
3. Place the 3M™ V.A.C.® Therapy Unit and power cords in the black hard-plastic case.
4. Place black hard-plastic case into blue return bag.
5. Drop off at any local UPS Store *or* call 3M at 1-800-275-4524, press 2, dial 45995 to schedule a pickup at no cost to you.

If the black hard-plastic case and/or blue return bag have been misplaced or lost, please call 3M at 1-800-275-4524 for assistance at no charge to you.